

		/	/		
<b>HF612IG5C</b>		<b>F2H0624HB</b>	<b>HPT INLSIRAL S p A</b>	<b>TK0807</b>	<b>NE3 2</b>
<b>HF6120K0D1E5</b>		<b>ISL9 5 310E1A</b>		<b>FR9180</b>	<b>CM280</b>
<b>HF6700DE5B</b>		<b>ISF2 8:514E</b>		<b>SC98975</b>	<b>CM220</b>
<b>HF6700DE5B</b>		<b>ISF3 8:514I</b>		<b>SC98980</b>	<b>CM220</b>
<b>HF610HQ5</b>		<b>B6 70E5 210</b>		<b>67210</b>	<b>RCMH</b>
<b>HF612IG5C</b>		<b>B65 230</b>		<b>FR92955</b>	<b>481710</b>
<b>HF6120G01C</b>		<b>ISLGEV 280</b>		<b>FR92827</b>	<b>481710</b>
<b>HF6700DE5B1</b>		<b>HG1E1- 1D</b>		<b>P1466</b>	<b>HC17</b>
<b>HF654IKQ4</b>		<b>HG1A1- C</b>		<b>M20L2</b>	<b>M20L2</b>
<b>HF658IK5</b>		<b>4D08 81E5</b>		<b>3601603 B0</b>	<b>3601115 B0</b>
<b>HF6115G01C</b>		<b>C66L2 29E5N</b>		<b>100009 25L</b>	<b>HD4G</b>
<b>HF6850DE5B</b>		<b>CAD1- 18E5</b>		<b>3601600 7E5</b>	<b>C31</b>
<b>HF6770DE5B1</b>		<b>CADD 17E5</b>		<b>3601603 C21</b>	<b>HFPO7A</b>
<b>HF6700DE5B1</b>		<b>RA28Q36E50</b>		<b>52513682</b>	<b>WHIC7</b>
<b>HF6700DE5B1</b>		<b>RA28Q50E50</b>		<b>52815082</b>	<b>WHIC7</b>

HF6120A12	W10 33E55		6 1265IE-11	VHIC7
HF6153E01C	W10NG28E50	( )	W10NG_33	8237 1104
HF614008CE5	W10NG30E51	( )	W10NG_35	8237 1104
HF6141K07DIE5	W12 40E50		51240019	VHIC7
HF618002CE5	W12NG33E50	( )	W12NG_35	8237 1104
HF6750KDE5B	W4 1QJ5E50		50415036	VHIC7
HF6819KDE5B	W4 1QJ6E50		50416536	VHIC7
HF6819KDE5B	W5 20E51		50520021	VHIC7
HK650HQ5	W5NG18E50	( )	W5NG_31	8237 1104
HF610008CHE23	W7NG24E51		W7NG_36	8237 1104
HF6123K0E5	Y6NR30N 50		NE50	YCCU
HF6908KDE5B	Y6E25 5B		J5R00	HDI7
HF6859KDE5B	Y6E20 5B		J5I00	HDI7
HF6750KDE5B	Y6S150 50		SC200	HDI6/17

<b>HF501NLJQ</b>		<b>4 SL</b>	<b>River Solutions International, Inc</b>	<b>3A30024</b>	<b>NFB</b>
<b>HF666K5</b>		<b>C4EK51</b>		<b>ISO5Q08</b>	<b>HDI7A54</b>
<b>HF666K5</b>		<b>C4EK51</b>		<b>ISO5Q08</b>	<b>HDI7A54</b>
<b>HF666K5</b>		<b>C4EK51</b>		<b>ISO5Q15</b>	<b>HDI7A54</b>
<b>HF666K5</b>		<b>C4EK51</b>		<b>ISO5Q15</b>	<b>HDI7A54</b>
<b>HF508N75</b>		<b>NFB O CS5A</b>		<b>ISO8Q01</b>	<b>E17</b>
<b>HF600K5FB2</b>		<b>NFB O CS5A</b>		<b>ISO8Q01</b>	<b>E17</b>
<b>HF600K5FB</b>		<b>NFB O CS5A</b>		<b>ISO8Q01</b>	<b>E17</b>
<b>HF600K5FB1</b>		<b>NFB O CS5A</b>		<b>ISO8Q01</b>	<b>E17</b>
<b>HK689Q</b>		<b>NJ20B5</b>		<b>36 3Z 01012 B01</b>	<b>36 3Z 01011 A01</b>
<b>HK601C5</b>		<b>NJ20B5</b>		<b>36 3Z 01012 B01</b>	<b>36 3Z 01011 A01</b>
<b>HF668CC5FB</b>		<b>NJ20B5</b>		<b>36 3Z 01012 B01</b>	<b>36 3Z 01011 A01</b>
<b>HK689Q</b>		<b>NJ20B5</b>		<b>36 3Z 01012 B01</b>	<b>36 3Z 01011 A01</b>
<b>HK689Q</b>		<b>NJ20B5</b>		<b>36 3Z 01012 B01</b>	<b>36 3Z 01011 A01</b>
<b>HF655K5</b>		<b>HC2DF1 2D1</b>		<b>ISO2SQ02</b>	<b>HDI7A54</b>
<b>HF669K5</b>		<b>HC2DF1 2D1</b>		<b>ISO2SQ02</b>	<b>HDI7A54</b>
<b>HF658K5</b>		<b>HC2DF1 2D1</b>		<b>ISO2SQ02</b>	<b>HDI7A54</b>
<b>HF658K5</b>		<b>HC2DF1 2D1</b>		<b>ISO2SQ02</b>	<b>HDI7A54</b>
<b>HF666K5</b>		<b>HC2DF1 2D2</b>		<b>ISO2SQ02</b>	<b>HDI7A54</b>

<b>HF666K85</b>		<b>HC1F1 2D2</b>		<b>HS02SQ02</b>	<b>HC17A54</b>
<b>HF670KQ4B1</b>		<b>HC1A3 4C</b>		<b>ME2 1</b>	<b>ME2 1</b>
<b>HF670KQ4B</b>		<b>HC1A3 4C</b>		<b>ME2 1</b>	<b>ME2 1</b>
<b>HF680KQ4B</b>		<b>HC1A3 4C</b>		<b>ME2 1</b>	<b>ME2 1</b>
<b>HF6105G3C</b>		<b>C68F2 23FN</b>		<b>330103D 4A8</b>	<b>HD4G</b>
<b>HF6105H4S</b>		<b>C68F2 23FN</b>		<b>330103D 4A8</b>	<b>HD4G</b>
<b>HF610008CHEM26</b>		<b>C68F2 21FN</b>		<b>330103D 4A7</b>	<b>HD4G</b>
<b>HF610008PHE2</b>		<b>C68F2 21FN</b>		<b>330103D 4A7</b>	<b>HD4G</b>
<b>HF691H4S</b>		<b>C68F2 21FN</b>		<b>330103D 4A7</b>	<b>HD4G</b>
<b>HF690H4S</b>		<b>C68F2 21FN</b>		<b>330103D 4A7</b>	<b>HD4G</b>
<b>HF6115G3C</b>		<b>C68L2 21FN</b>		<b>100008B25L</b>	<b>HD4G</b>
<b>HF668K05FB</b>		<b>D5K0E3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF668K05FB1</b>		<b>D5K0E3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF668K05FB</b>		<b>D5K0E3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF6680E5FB</b>		<b>D5K0E3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF6680E5FB</b>		<b>D5K0E3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF66010E5FB</b>		<b>D5K0E3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF660K25</b>		<b>D5K0E3</b>		<b>V72 6</b>	<b>HC</b>

<b>HF666IK5</b>		<b>D5KIE3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF666IK5</b>		<b>D5KIE3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF669KDE5BI</b>		<b>D5KIE3</b>		<b>V72 6</b>	<b>HC</b>
<b>HF680IK5</b>		<b>D8KIE1</b>		<b>V72 1</b>	<b>HC</b>
<b>HF680IK5</b>		<b>D8KIE1</b>		<b>V72 1</b>	<b>HC</b>
<b>HF675KDE5B</b>		<b>D8KIE1</b>		<b>V72 1</b>	<b>HC</b>
<b>HF673KDE5BI</b>		<b>D8KIE2</b>		<b>V72 2</b>	<b>HC</b>
<b>HF673KDE5B</b>		<b>D8KIE2</b>		<b>V72 2</b>	<b>HC</b>
<b>HF673KDE5B</b>		<b>D8KIE2</b>		<b>V72 2</b>	<b>HC</b>
<b>HF674IK5</b>		<b>D8KIE2</b>		<b>V72 2</b>	<b>HC</b>
<b>HF674IK5</b>		<b>D8KIE2</b>		<b>V72 2</b>	<b>HC</b>
<b>HF658IK5</b>		<b>YN2RE1</b>		<b>HC 271</b>	<b>HC</b>
<b>HF658IK5</b>		<b>YN2RE1</b>		<b>HC 271</b>	<b>HC</b>
<b>HK669Q</b>		<b>YN6QE</b>		<b>NC88</b>	<b>NC88</b>
<b>HK669Q</b>		<b>YN6QE</b>		<b>NC88</b>	<b>NC88</b>
<b>HF669KDE5B</b>		<b>YN6QE</b>		<b>NC88</b>	<b>NC88</b>
<b>HK669Q</b>		<b>YN6QE</b>		<b>NC88</b>	<b>NC88</b>
<b>HK669Q</b>		<b>YN6QE</b>		<b>NC88</b>	<b>NC88</b>
<b>HF65008DE5</b>		<b>YN4IE1</b>		<b>OSNEAP E1</b>	<b>DMG 24</b>

<b>HF65008CHEM1</b>		<b>YN40E1</b>		<b>OSNFAP E1</b>	<b>DUG 24</b>
<b>HF6120K08DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6120K40DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6120K08DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6121K06DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6120K08DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6121K08DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6120A12</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6120K10DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6123K06DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6113K06DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6113K06DIE5</b>		<b>W10 33E53</b>		<b>5103619</b>	<b>WHC7</b>
<b>HF6120K40DIE5</b>		<b>W10 37E53</b>		<b>5103519</b>	<b>WHC7</b>
<b>HF6121K06DIE5</b>		<b>W10 37E53</b>		<b>5103519</b>	<b>WHC7</b>
<b>HF6120K40DIE5</b>		<b>W10 37E53</b>		<b>5103519</b>	<b>WHC7</b>
<b>HF6120K08DIE5</b>		<b>W10 37E53</b>		<b>5103519</b>	<b>WHC7</b>
<b>HF6121K06DIE5</b>		<b>W10 37E53</b>		<b>5103519</b>	<b>WHC7</b>
<b>HF6120K08DIE5</b>		<b>W10 37E53</b>		<b>5103519</b>	<b>WHC7</b>

HF6120A92		W10B75E50		510B7521	WHC7
HF6120A95		W10B75E50		510B7521	WHC7
HF6120A98		W10B75E50		510B7521	WHC7
HF6113K082E5		W10NG336E50		W10NG_31	8237 1104
HF6120K08C1E5		W10NG336E50		W10NG_31	8237 1104
HF6121K08C1E5		W10NG336E50		W10NG_31	8237 1104
HF6121K08C2E5		W10NG336E50		W10NG_31	8237 1104
HF6120K08C2E5		W10NG336E50		W10NG_31	8237 1104
HF6120K10C2E5		W10NG336E50	( )	W10NG_31	8237 1104
HF6120K10C1E5		W10NG336E50	( )	W10NG_31	8237 1104
HF6120K08C2E5		W10NG336E50	( )	W10NG_31	8237 1104
HF6113K08C1E5		W10NG336E50		W10NG_31	8237 1104
HF6120K08C1E5		W10NG336E50		W10NG_31	8237 1104
HF6121K08C1E5		W10NG336E50		W10NG_31	8237 1104
HF6123K10C1		W10NG336E50	( )	W10NG_31	8237 1104
HF6121K08C2		W10NG336E50	( )	W10NG_31	8237 1104
HF6123K10C2		W12NG380E50		W12NG_31	8237 1104
HF6123K10C3		W12NG380E50		W12NG_31	8237 1104
HF5080AC5		W2 1Q5E50		5219532	WHC7

<b>HF658IK5</b>		<b>W2 1Q5E50</b>		<b>5219532</b>	<b>WHIC7</b>
<b>HF658IK5</b>		<b>W2 1Q5E50</b>		<b>5219532</b>	<b>WHIC7</b>
<b>HF668KD5BI</b>		<b>W3 7Q13E50</b>		<b>5371329</b>	<b>WHIC7</b>
<b>HF668KD5B</b>		<b>W3 7Q13E50</b>		<b>5371329</b>	<b>WHIC7</b>
<b>HF668DE5B</b>		<b>W3 7Q13E50</b>		<b>5371329</b>	<b>WHIC7</b>
<b>HF668DE5B</b>		<b>W3 7Q13E50</b>		<b>5371329</b>	<b>WHIC7</b>
<b>HF668KD5BI</b>		<b>W3 7Q13E50</b>		<b>5371329</b>	<b>WHIC7</b>
<b>HF6739DE5BI</b>		<b>W3 7Q30E50</b>		<b>5371309</b>	<b>WHIC7</b>
<b>HF6739DE5B</b>		<b>W3 7Q30E50</b>		<b>5371309</b>	<b>WHIC7</b>
<b>HF680IK5</b>		<b>W3 7Q30E50</b>		<b>5371309</b>	<b>WHIC7</b>
<b>HF680IK51</b>		<b>W3 7Q30E50</b>		<b>5371309</b>	<b>WHIC7</b>
<b>HF680IK51</b>		<b>W3 7Q30E50</b>		<b>5371309</b>	<b>WHIC7</b>
<b>HF674IK5</b>		<b>W3 7Q30E50</b>		<b>5371309</b>	<b>WHIC7</b>
<b>HF674IK5</b>		<b>W3 7Q30E50</b>		<b>5371309</b>	<b>WHIC7</b>
<b>HF670KD5B</b>		<b>W3Q30E50</b>		<b>5081308</b>	<b>WHIC7</b>
<b>HF670DE5B</b>		<b>W3Q30E50</b>		<b>5081308</b>	<b>WHIC7</b>
<b>HF674IK5</b>		<b>W3Q30E50</b>		<b>5081308</b>	<b>WHIC7</b>
<b>HF674IK5</b>		<b>W3Q30E50</b>		<b>5081308</b>	<b>WHIC7</b>
<b>HF677IKDE5BI</b>		<b>W4 1Q40E50</b>		<b>5041406</b>	<b>WHIC7</b>

<b>HF685008CHEM</b>		<b>VP4 1Q40E50</b>		<b>5044026</b>	<b>VHIC7</b>
<b>HF6881K25</b>		<b>VP4 1Q40E50</b>		<b>5044026</b>	<b>VHIC7</b>
<b>HF68100DE5B</b>		<b>VP4 1Q60E50</b>		<b>5046026</b>	<b>VHIC7</b>
<b>HF67700DE5B</b>		<b>VP4 1Q60E50</b>		<b>5046026</b>	<b>VHIC7</b>
<b>HF6101K25</b>		<b>VP4 1Q60E50</b>		<b>5046026</b>	<b>VHIC7</b>
<b>HF6101K25</b>		<b>VP4 1Q60E50</b>		<b>5046026</b>	<b>VHIC7</b>
<b>HF6861K25</b>		<b>VP4 1Q60E50</b>		<b>5046026</b>	<b>VHIC7</b>
<b>HF68500DE5B</b>		<b>VS5 180E51</b>		<b>50518021</b>	<b>VHIC7</b>
<b>HF6111K25</b>		<b>VS5 180E51</b>		<b>50518021</b>	<b>VHIC7</b>
<b>HF69400DE5B</b>		<b>VS5 220E51</b>		<b>50522021</b>	<b>VHIC7</b>
<b>HF6111K25</b>		<b>VS5 220E51</b>		<b>50522021</b>	<b>VHIC7</b>
<b>HF6859K0E5B</b>		<b>VS5 220E51</b>		<b>50522021</b>	<b>VHIC7</b>
<b>HK6770HQ5</b>		<b>VS5NG16E50</b>	<b>( )</b>	<b>VS5NG_32</b>	<b>8237 1104</b>
<b>HK6813HQ5</b>		<b>VS5NG16E50</b>	<b>( )</b>	<b>VS5NG_32</b>	<b>8237 1104</b>
<b>HF6859K0E5B</b>		<b>VS6 220E50</b>		<b>50622023</b>	<b>VHIC7</b>
<b>HF6108008CHEV 1</b>		<b>VS6 220E50</b>		<b>50622023</b>	<b>VHIC7</b>
<b>HF6100008CHEM3</b>		<b>VS6 220E50</b>		<b>50622023</b>	<b>VHIC7</b>

<b>HF600K08D5</b>		<b>W6 24550</b>		<b>5084523</b>	<b>WHC7</b>
<b>HF608K05B</b>		<b>W6 24550</b>		<b>5084523</b>	<b>WHC7</b>
<b>HF610061D5</b>		<b>W6 24550</b>		<b>5084523</b>	<b>WHC7</b>
<b>HF6000D5B</b>		<b>W6 24550</b>		<b>5084523</b>	<b>WHC7</b>
<b>HF61000D5B</b>		<b>W6 24550</b>		<b>5084523</b>	<b>WHC7</b>
<b>HF6109D5B</b>		<b>W6 24550</b>		<b>5084523</b>	<b>WHC7</b>
<b>HF61003D5</b>		<b>W6 24550</b>		<b>5084523</b>	<b>WHC7</b>
<b>HF608K01E5B</b>		<b>W6 24550</b>		<b>5084523</b>	<b>WHC7</b>
<b>HK60H15</b>		<b>W6N21050</b>	<b>( )</b>	<b>W6N_32</b>	<b>8237 1104</b>
<b>HK61H15</b>		<b>W6N21050</b>	<b>( )</b>	<b>W6N_32</b>	<b>8237 1104</b>
<b>HF6108008CHEV 2</b>		<b>W6N21050</b>		<b>W6N_32</b>	<b>8237 1104</b>
<b>HF6123008CHEV 2</b>		<b>W6N21050</b>		<b>W6N_32</b>	<b>8237 1104</b>
<b>HF608K01E5B</b>		<b>W6N21050</b>		<b>W6N_31</b>	<b>8237 1104</b>
<b>HF608K05B</b>		<b>W6N21050</b>		<b>W6N_31</b>	<b>8237 1104</b>
<b>HF680K68C1E5</b>		<b>W6N21050</b>		<b>W6N_31</b>	<b>8237 1104</b>
<b>HF600K08C1E5B</b>		<b>W6N21050</b>		<b>W6N_31</b>	<b>8237 1104</b>
<b>HK6105H15</b>		<b>W6N21050</b>	<b>( )</b>	<b>W6N_31</b>	<b>8237 1104</b>
<b>HF600K08C2E5</b>		<b>W6N21050</b>	<b>( )</b>	<b>W6N_31</b>	<b>8237 1104</b>

HF600K8CIE5		WNG20E50	( )	WNG_31	8237 1104
HF610K10DIE5		W7 270E51		5072021	WHC7
HF612000IDE5		W7 270E51		5072021	WHC7
HF6109DE5B		W7 270E51		5072021	WHC7
HF6110K10DIE5		W7 270E51		5072021	WHC7
HF6110G80IDE5		W7 270E51		5072021	WHC7
HF6119DE5B		W7 270E51		5072021	WHC7
HF6110K08DIE5B		W7 270E51		5072021	WHC7
HF6119DE5B		W7 270E55		5072021	WHC7
HF6110K08DIE5B		W7 270E55		5072021	WHC7
HF6110K08DIE5		W7 300E51		5073021	WHC7
HF610K10DIE5		W7 300E51		5073021	WHC7
HF6105G3C		WNG20E50		WNG_33	8237 1104
HF6115G5C		WNG20E50		WNG_33	8237 1104
HF6115G5C		WNG30E50		WNG_32	8237 1104
HF6100K8CIE5		WNG30E50		WNG_32	8237 1104
HF600K8C2E5		WNG30E50	( )	WNG_32	8237 1104
HF6125GZ 4C		WNG30E50		WNG_32	8237 1104
HF6110K10CIE5		WNG270E50		WNG_31	8237 1104

<b>HF610068C2E5</b>		<b>W7NG20E50</b>	<b>( )</b>	<b>W7NG_31</b>	<b>8237 1104</b>
<b>HF610090C2E5</b>		<b>W7NG20E50</b>	<b>( )</b>	<b>W7NG_31</b>	<b>8237 1104</b>
<b>HF6111K08C1E5</b>		<b>W7NG20E51</b>		<b>W7NG_31</b>	<b>8237 1104</b>
<b>HF610090C1E5B</b>		<b>W7NG20E51</b>		<b>W7NG_31</b>	<b>8237 1104</b>
<b>HF610090C1E5</b>		<b>W7NG20E51</b>		<b>W7NG_31</b>	<b>8237 1104</b>
<b>HG609Q</b>		<b>YQD14N 50</b>		<b>DA00</b>	<b>YCCU</b>
<b>HG601CQ</b>		<b>YQD14N 50</b>		<b>DA00</b>	<b>YCCU</b>
<b>HF66090C1E5B</b>		<b>YQD14N 50</b>		<b>DA00</b>	<b>YCCU</b>
<b>HG639CQ</b>		<b>YQD14N 50</b>		<b>DA00</b>	<b>YCCU</b>
<b>HF665008CHE2</b>		<b>YQD14N 50</b>		<b>DA00</b>	<b>YCCU</b>
<b>HG670H1Q</b>		<b>YQD14N 50</b>		<b>DA00</b>	<b>YCCU</b>
<b>HF6105G3C</b>		<b>SG8D1230Q</b>		<b>G5 230</b>	<b>G5 ECU</b>
<b>HF6115G5C</b>		<b>SG8D1230Q</b>		<b>G5 230</b>	<b>G5 ECU</b>
<b>HF6115G6C</b>		<b>SG8D1230Q</b>		<b>G5 230</b>	<b>G5 ECU</b>
<b>HF66080E5B</b>		<b>YQFA115 50</b>		<b>FC00</b>	<b>HD16/17</b>
<b>HF5010X5</b>		<b>YQFA115 50</b>		<b>FC00</b>	<b>HD16/17</b>
<b>HF5010X15</b>		<b>YQFA115 50</b>		<b>FC00</b>	<b>HD16/17</b>
<b>HF66080E5B</b>		<b>YQFA115 50</b>		<b>FC00</b>	<b>HD16/17</b>

<b>HF669KD5B1</b>		<b>YCF115 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669KD5B</b>		<b>YCF115 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669CD5B</b>		<b>YCF115 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669CD5B</b>		<b>YCF115 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF661K5</b>		<b>YCF115 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF661K5</b>		<b>YCF115 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF670KD5B</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF6739CD5B1</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF6739KD5B</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669KD5B1</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669KD5B</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669CD5B</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669CD5B</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669CD5B</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669KD5B</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF6739CD5B</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF669KD5B1</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF6741K5</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF6741K5</b>		<b>YCF130 50</b>		<b>RC00</b>	<b>HD16/17</b>
<b>HF6850CD5B</b>		<b>YCF180 50</b>		<b>YCF180 50</b>	<b>HC7</b>

<b>HF68100E5B</b>		<b>YC1G180 50</b>		<b>YC1G180 50</b>	<b>HC7</b>
<b>HF6850HQ5</b>		<b>YC1G180N 50</b>		<b>G2R0</b>	<b>YCCU</b>
<b>HF6813HQ5</b>		<b>YC1G180N 50</b>		<b>G2R0</b>	<b>YCCU</b>
<b>HF6819K0E5B1</b>		<b>YC1G200 50</b>		<b>YC1G200 50</b>	<b>HC7</b>
<b>HF6819K0E5B</b>		<b>YC1G200 50</b>		<b>YC1G200 50</b>	<b>HC7</b>
<b>HF6859K0E5B</b>		<b>YC1G220 50</b>		<b>YC1G220 50</b>	<b>HC7</b>
<b>HF6819K0E5B1</b>		<b>YC1G220 50</b>		<b>YC1G220 50</b>	<b>HC7</b>
<b>HF6859K0E5B</b>		<b>YC1G220 50</b>		<b>YC1G220 50</b>	<b>HC7</b>
<b>HF6809K0E5B</b>		<b>Y6G270 50</b>		<b>A500</b>	<b>HC7</b>
<b>HF6101G30E5</b>		<b>Y6G270 50</b>		<b>A500</b>	<b>HC7</b>
<b>HF6101K10E5</b>		<b>Y6G270 50</b>		<b>A500</b>	<b>HC7</b>
<b>HF6110G50E5</b>		<b>Y6G230N 50</b>		<b>G380</b>	<b>YCCU</b>
<b>HF6801K08C2E5</b>		<b>Y6G230N 50</b>		<b>G380</b>	<b>YCCU</b>
<b>HF6800K08C1E5</b>		<b>Y6G230N 50</b>		<b>G380</b>	<b>YCCU</b>
<b>HF6100G30E5</b>		<b>Y6G230N 50</b>		<b>G380</b>	<b>YCCU</b>
<b>HF6800K08C1E5B</b>		<b>Y6G230N 50</b>		<b>G380</b>	<b>YCCU</b>
<b>HF6110CE5B</b>		<b>Y6G230N 50</b>		<b>G3R0</b>	<b>YCCU</b>
<b>HF6120CE5B</b>		<b>Y6G230N 50</b>		<b>G3R0</b>	<b>YCCU</b>
<b>HF6105HQ5</b>		<b>Y6G230N 50</b>		<b>G3R0</b>	<b>YCCU</b>

<b>HF600K8C2E5</b>		<b>Y628N 50</b>		<b>G300</b>	<b>YCCU</b>
<b>HF610K6C1E5</b>		<b>Y628N 50</b>		<b>G300</b>	<b>YCCU</b>
<b>HF610K10C1E5</b>		<b>Y628N 50</b>		<b>G300</b>	<b>YCCU</b>
<b>HF69100E5B</b>		<b>Y6200 50</b>		<b>J5N0</b>	<b>HC7</b>
<b>HF610K5</b>		<b>Y6200 50</b>		<b>J5N0</b>	<b>HC7</b>
<b>HF5130N1E5</b>		<b>Y6200 50</b>		<b>J5N0</b>	<b>HC7</b>
<b>HF69000E5B</b>		<b>Y6200 50</b>		<b>J5N0</b>	<b>HC7</b>
<b>HK600HQ5</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HK691HQ5</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HF612208CHE2</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HF6859K1E5B</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HF610008CHE22</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HF6859K1E5B</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HF610008CHE24</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HF6121008CHEV 22</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HF6100G8CE5</b>		<b>Y6210N 52</b>		<b>J400</b>	<b>YCCU</b>
<b>HF612208CHEM</b>		<b>Y6220 52</b>		<b>JC00</b>	<b>HC7</b>

<b>HF610008CHEM2</b>		<b>Y6120 52</b>		<b>JC00</b>	<b>HC7</b>
<b>HF610008CHEM1</b>		<b>Y6120 52</b>		<b>JC00</b>	<b>HC7</b>
<b>HF65580IE5B</b>		<b>Y6120 52</b>		<b>JC00</b>	<b>HC7</b>
<b>HF610039IE5</b>		<b>Y6125 50</b>		<b>JO10</b>	<b>HC7</b>
<b>HF61000IE5B</b>		<b>Y6125 50</b>		<b>JO10</b>	<b>HC7</b>
<b>HF610068IE5</b>		<b>Y6125 52</b>		<b>JO10</b>	<b>HC7</b>
<b>HF610169IE5</b>		<b>Y6125 52</b>		<b>JO10</b>	<b>HC7</b>
<b>HF611560C</b>		<b>Y6121N 52</b>		<b>IN00</b>	<b>YCCU</b>
<b>HF610562C</b>		<b>Y6121N 52</b>		<b>IN00</b>	<b>YCCU</b>
<b>HF611061IE5</b>		<b>Y61260 50</b>		<b>LA00</b>	<b>HC7</b>
<b>HF610061IE5</b>		<b>Y61260 50</b>		<b>LA00</b>	<b>HC7</b>
<b>HF6115601C</b>		<b>Y6126N 52</b>		<b>IN00</b>	<b>YCCU</b>
<b>HF61256Z 4C</b>		<b>Y6126N 52</b>		<b>IN00</b>	<b>YCCU</b>
<b>HF611068IE5</b>		<b>Y61280 50</b>		<b>LA300</b>	<b>HC7</b>
<b>HF612001IE5</b>		<b>Y61280 50</b>		<b>LA300</b>	<b>HC7</b>
<b>HF6110680IE5</b>		<b>Y61280 50</b>		<b>LA300</b>	<b>HC7</b>
<b>HF6120601C</b>		<b>Y6128N 52</b>		<b>IN00</b>	<b>YCCU</b>

<b>HF611K08CIE5</b>		<b>Y6L28N 52</b>		<b>IND0</b>	<b>YCCU</b>
<b>HF610K10C2E5</b>		<b>Y6L28N 52</b>		<b>IND0</b>	<b>YCCU</b>
<b>HF6182C02D</b>		<b>Y6L310 50</b>		<b>LA200</b>	<b>HC7</b>
<b>HF610K08DIE5</b>		<b>Y6L310 50</b>		<b>LA300</b>	<b>HC7</b>
<b>HF6120K10DIE5</b>		<b>Y6L330 50</b>		<b>LA100</b>	<b>HC7</b>
<b>HF6123K08DIE5</b>		<b>Y6L330 50</b>		<b>LA100</b>	<b>HC7</b>
<b>HF6113K08DIE5</b>		<b>Y6L330 50</b>		<b>LA100</b>	<b>HC7</b>
<b>HF6113K08DE5</b>		<b>Y6L330 50</b>		<b>LA100</b>	<b>HC7</b>
<b>HF6120K08DIE51</b>		<b>Y6L330 50</b>		<b>LA100</b>	<b>HC7</b>
<b>HF6121K08DIE51</b>		<b>Y6L330 50</b>		<b>LA100</b>	<b>HC7</b>
<b>HF6121K08DIE5</b>		<b>Y6L330 50</b>		<b>LA100</b>	<b>HC7</b>
<b>HF6120A91</b>		<b>Y6L330 58</b>		<b>IF100</b>	<b>HC7</b>
<b>HF6120K08DIE51</b>		<b>Y6L330 58</b>		<b>IF100</b>	<b>HC7</b>
<b>HF6121K08DIE51</b>		<b>Y6L330 58</b>		<b>IF100</b>	<b>HC7</b>
<b>HF6121K08C2</b>		<b>Y6N34N 50</b>		<b>M300</b>	<b>YCCU</b>
<b>HF6120K10C2E5</b>		<b>Y6N34N 50</b>		<b>M300</b>	<b>YCCU</b>
<b>HF6120K10CIE5</b>		<b>Y6N34N 50</b>		<b>M300</b>	<b>YCCU</b>
<b>HF6120K08C2E5</b>		<b>Y6N34N 50</b>		<b>M300</b>	<b>YCCU</b>
<b>HF6113K08CIE5</b>		<b>Y6N34N 50</b>		<b>M300</b>	<b>YCCU</b>

<b>HF612K08C1E5</b>		<b>YG6N31N 5D</b>		<b>M30D</b>	<b>YCCU</b>
<b>HF612K08C1E5</b>		<b>YG6N31N 5D</b>		<b>M30D</b>	<b>YCCU</b>
<b>HF6123K40C1</b>		<b>YG6N375N 5D</b>		<b>M10D</b>	<b>YCCU</b>
<b>HF6123K40C2</b>		<b>YG6N375N 5D</b>		<b>M10D</b>	<b>YCCU</b>
<b>HF6123K40C3</b>		<b>YG6N375N 5D</b>		<b>M10D</b>	<b>YCCU</b>
<b>HF612K41EV 1</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF612K41EV 2</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF612K41EV 3</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF612K41EV 4</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF612K41EV 6</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF612K41EV 5</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF680HEVX</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF680HEV</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF610K1CEV</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF610K1CEV 1</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF610K1CEV 2</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF611K1CEV</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF6700BEV</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>
<b>HF6701BEV</b>		<b>AKCU 1</b>		<b>905D</b>	<b>ECU V2 0</b>

<b>HF6704BEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6705BEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6708BEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6707BEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6707BEM</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6708BEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6108KICEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6108KICEV 3</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6800GEM</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6800GEM</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6800GEM6</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6850KICEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6851KICEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6808KICEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6108K10EM</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6111K10EM</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6830HEV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6108KICEV 1</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6111K10E2</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>

<b>HF611K1CEV</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF611K1CEV3</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6123K1CEV 1</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6800CEV</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6800CEM</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6829CEMB</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6829CEM1</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6129C08EV 41</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6129C08EV 42</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6109C08EM1</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6101C08EV4</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6109K1CEV31</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF611K1CEV31</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6800C08EV7</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6800C08EM8</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6101C08EM6</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF611K1CEV21</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6808CEMB</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>
<b>HF6808CEMB</b>	<b>AKCU 1</b>	<b>9050</b>	<b>ECU V2 0</b>

<b>HF610908EV3</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF610108EV21</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF610908EV4</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF610908EV2</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF610008EV 6</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6109K10EV31</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF685308EV1</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF680008EV61</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF680008EV9</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF682908EV3</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF612908EV 43</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF610008EV 7</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF680008EV73</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF612108EV3</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF612908EV 45</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF610908EV5</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF610008EV 61</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF680008EV4</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6121608EV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>

<b>HF6800GEM3</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF504IXSEM1</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6800GEM9</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6121GS08EV</b>		<b>AKCU 1</b>		<b>9050</b>	<b>ECU V2 0</b>
<b>HF6600GEM1</b>		<b>AKCU 1</b>		<b>10507</b>	<b>ECU V2 0</b>
<b>HF6600GEM2</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6600GEM21</b>		<b>AKCU 1</b>		<b>10456</b>	<b>ECU V2 0</b>
<b>HF6600GEM22</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6650GEM1</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6650GEM11</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6650GEM32</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6650GEM33</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6650GEM21</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6668GEM1</b>		<b>AKCU 1</b>		<b>10557</b>	<b>ECU V2 0</b>
<b>HF6800GEM64</b>		<b>AKCU 1</b>		<b>10861</b>	<b>ECU V2 0</b>
<b>HF6800GEM65</b>		<b>AKCU 1</b>		<b>9888</b>	<b>ECU V2 0</b>
<b>HF6800GEM78</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6800GEM79</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6800GEM21</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>

**HF6800GEV21**

**AKCU 1**

**10974**

**ECU V2 0**

**HF6800GEV22**

**AKCU 1**

**10974**

**ECU V2 0**

**HF685400EV**

<b>HF6120GEV31</b>		<b>AKCU 1</b>		<b>10861</b>	<b>ECU V2 0</b>
<b>HF6120HEV22</b>		<b>AKCU 1</b>		<b>10861</b>	<b>ECU V2 0</b>
<b>HF6121G08EM1</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF66008EV21</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6829GEV2</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6829GEV</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF68296EV21</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6829HEV</b>		<b>AKCU 1</b>		<b>10861</b>	<b>ECU V2 0</b>
<b>HF68296EV22</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6119GEV2</b>		<b>AKCU 1</b>		<b>10557</b>	<b>ECU V2 0</b>
<b>HF6119HEV2</b>		<b>AKCU 1</b>		<b>10557</b>	<b>ECU V2 0</b>
<b>HF61106EV21</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF61106EV22</b>		<b>AKCU 1</b>		<b>10861</b>	<b>ECU V2 0</b>
<b>HF61196EM1</b>		<b>AKCU 1</b>		<b>10861</b>	<b>ECU V2 0</b>
<b>HF61196EV23</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF61196EV24</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF61196EV25</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF61196EV21</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6113HEV2</b>		<b>AKCU 1</b>		<b>10861</b>	<b>ECU V2 0</b>

<b>HF6123KCEV</b>		<b>AKCU 1</b>		<b>1009</b>	<b>ECU V2 0</b>
<b>HF682IKEM</b>		<b>AKCU 1</b>		<b>1009</b>	<b>ECU V2 0</b>
<b>HF6710BEV</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6710KZE21</b>		<b>AKCU 1</b>		<b>10974</b>	<b>ECU V2 0</b>
<b>HF6530QE21</b>		<b>AKCU 1</b>		<b>10861</b>	<b>ECU V3 0</b>
<b>HF68500E6</b>		<b>VW1 6NG200E60</b>		<b>VWSD101570</b>	<b>VWSE11</b>
<b>HF6800G7D6</b>		<b>VW2 3NQ30E61</b>		<b>602130B2Q</b>	<b>VWSE15</b>
<b>HF6800G7D6</b>		<b>YC21140 60A</b>		<b>YC21140 60A</b>	<b>YKCU 011</b>
<b>HF6730G7D6</b>		<b>YC21140 60</b>		<b>YC21140 60</b>	<b>YKCU 011</b>
<b>HF6581K6</b>		<b>VW2 3NQ20E61</b>		<b>602120B2Q</b>	<b>VWSE15</b>
<b>HF65808E6Y</b>		<b>VW2 3NQ20E61</b>		<b>602120B2Q</b>	<b>VWSE15</b>
<b>HF6581S6DK</b>		<b>YC21120 60</b>		<b>YC21120 60</b>	<b>YKCU 011</b>
<b>HF6581S6EY</b>		<b>YC21120 60</b>		<b>YC21120 60</b>	<b>YKCU 011</b>
<b>HF68057DK</b>		<b>VW2 3NQ30E61</b>		<b>602130B2Q</b>	<b>VWSE15</b>
<b>HF68057EY</b>		<b>VW2 3NQ30E61</b>		<b>602130B2Q</b>	<b>VWSE15</b>
<b>HF6740S7DK</b>		<b>YC21140 60</b>		<b>YC21140 60</b>	<b>YKCU 011</b>
<b>HF6740S7EY</b>		<b>YC21140 60</b>		<b>YC21140 60</b>	<b>YKCU 011</b>

<b>HF68089DZ</b>		<b>YX30165 60</b>		<b>YX30165 60</b>	<b>YKCU 011</b>
<b>HF610089DZ</b>		<b>YX04160 68</b>		<b>YX04160 68</b>	<b>YKCU 011</b>
<b>HF610089DX</b>		<b>YX04160 68</b>		<b>YX04160 68</b>	<b>YKCU 011</b>
<b>HF6111KZ6</b>		<b>VP4 6N22061</b>		<b>60422023Q</b>	<b>VISE15</b>
		<b>VP4 1N19061</b>		<b>60419036Q</b>	<b>VISE15</b>
<b>HF660F7DZ</b>		<b>YX24140 60</b>		<b>YX24140 60</b>	<b>YKCU 011</b>
<b>HF660KH6BB</b>		<b>YX24140 60</b>		<b>YX24140 60</b>	<b>YKCU 011</b>
<b>HF660KQ4BB</b>		<b>HC1G3 4C</b>		<b>ME2 1</b>	<b>ME2 1</b>
<b>HF670F7DZ</b>		<b>YX30150 60A</b>		<b>YX30150 60A</b>	<b>YKCU 011</b>
<b>HF6711KH6BB</b>		<b>YX30150 60A</b>		<b>YX30150 60A</b>	<b>YKCU 011</b>
<b>HF670NDZ</b>		<b>HC1D2 2E1</b>		<b>PI96B</b>	<b>NI1</b>
<b>HF670KQ4BB</b>		<b>HC1D1 3C</b>		<b>ME2 3</b>	<b>ME2 3</b>
<b>HF670KH6BB</b>		<b>N30 6F</b>		<b>46U</b>	<b>URN30F</b>
<b>HF670KH6BB</b>		<b>HC1D2 2E1</b>		<b>PI96B</b>	<b>NI1</b>
<b>HF670KQ4BB</b>		<b>HC1G3 4C</b>		<b>ME2 1</b>	<b>ME2 1</b>

<b>HR600KQ4B1</b>		<b>HC1A3 4C</b>		<b>ME2 1</b>	<b>ME2 1</b>
<b>HR600F7DZ</b>		<b>YC214D 60</b>		<b>YC214D 60</b>	<b>YFCU 011</b>
<b>HR606KQ6B</b>		<b>YC214D 60</b>		<b>YC214D 60</b>	<b>YFCU 011</b>
<b>HR606KQ4B</b>		<b>HC1A3 4C</b>		<b>ME2 1</b>	<b>ME2 1</b>
<b>HR670F7DZ</b>		<b>YC3015D 60A</b>		<b>YC214D 60</b>	<b>YFCU 011</b>
<b>HR671KQ6B</b>		<b>YC3015D 60A</b>		<b>YC214D 60</b>	<b>YFCU 011</b>
<b>HR614A1DXY</b>		<b>W10100B2</b>		<b>6101019</b>	<b>VSE15</b>
<b>HR6121A91</b>		<b>W10157B2</b>		<b>6105719</b>	<b>VSE15</b>
<b>HR6121A91</b>		<b>YK088D 61</b>		<b>YK088D 61</b>	<b>YFCU 011</b>
<b>HR6120K0D1B6</b>		<b>W1136B2</b>		<b>6083619</b>	<b>VSE15</b>
<b>HR6120K0D1B6</b>		<b>YK088D 60</b>		<b>YK088D 60</b>	<b>YFCU 011</b>
<b>HR680A1DXY</b>		<b>W7 270B1A</b>		<b>6072021A</b>	<b>VSE15</b>
<b>HR680K0D1B6</b>		<b>YK082D 62</b>		<b>YK082D 62</b>	<b>YFCU 011</b>
<b>HR6110A1DZ</b>		<b>YK083D 60</b>		<b>YK083D 60</b>	<b>YFCU 011</b>
<b>HR6119K0B</b>		<b>YK083D 60</b>		<b>YK083D 60</b>	<b>YFCU 011</b>
<b>HR678K0D1B6</b>		<b>W4 6N20B1</b>		<b>6022028Q</b>	<b>VSE15</b>
<b>HR650A1DZ</b>		<b>YK041D 68</b>		<b>YK041D 68</b>	<b>YFCU 011</b>

<b>HF610089DZ</b>		<b>YX30165 60</b>		<b>YX30165 60</b>	<b>YXCU 011</b>
<b>HF610089DK</b>		<b>YX30165 60</b>		<b>YX30165 60</b>	<b>YXCU 011</b>
<b>HF6730KSDZ</b>		<b>YX30150 60A</b>		<b>YX30150 60A</b>	<b>YXCU 011</b>
<b>HF6111A8DY</b>		<b>YK08330 60</b>		<b>YK08330 60</b>	<b>YXCU A3B</b>
<b>HF6581S6DK</b>		<b>YX24120 60</b>		<b>YX24120 60</b>	<b>YXCU 011</b>
<b>HF6581S6DY</b>		<b>YX24120 60</b>		<b>YX24120 60</b>	<b>YXCU 011</b>
<b>HF6120A9DY</b>		<b>W10E75E2</b>		<b>610E75I9</b>	<b>VSE15</b>
<b>HF6781A5DY</b>		<b>W4 6N220E1</b>		<b>6022028Q</b>	<b>VSE15</b>
<b>HF6601KQ1</b>		<b>HC1A3 4C</b>	<b>DIHH</b>	<b>M62 1</b>	<b>M62 1</b>
<b>HF686089DZ</b>		<b>YX30165 60</b>		<b>YX30165 60</b>	<b>YXCU 011</b>
<b>HF6900N8DY</b>		<b>W7 270E1A</b>		<b>60727021A</b>	<b>VSE15</b>
<b>HF6800S7DK</b>		<b>YX24140 60</b>		<b>YX24140 60</b>	<b>YXCU 011</b>
<b>HF6700N1D6</b>		<b>HC1E2 2E1</b>		<b>P196B</b>	<b>NM1</b>
<b>HF5170ISYD6</b>		<b>YK08310 60</b>		<b>YK08310 60</b>	<b>YXCU A3B</b>
<b>HF6820A5DY</b>		<b>YK05230 60</b>		<b>YK05230 60</b>	<b>YXCU A3B</b>

<b>HF6708GEM21</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6608GEM22</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6100E9FCEM32</b>	<b>AKCU 1</b>	<b>11608</b>	<b>ECU V2 0</b>
<b>HF6580QEM21</b>	<b>AKCU 1</b>	<b>11477</b>	<b>ECU V3 0</b>
<b>HF5010SMV</b>	<b>AKCU 1</b>	<b>11477</b>	<b>ECU V3 0</b>
<b>HF6100E9FCEM2</b>	<b>AKCU 1</b>	<b>11608</b>	<b>ECU V2 0</b>
<b>HF6101GEM21</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6708GEM1</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6708GEM22</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6600H6EM21</b>	<b>AKCU 1</b>	<b>11813</b>	<b>ECU V2 0</b>
<b>HF5010SSEM2</b>	<b>AKCU 1</b>	<b>11477</b>	<b>ECU V3 0</b>
<b>HF5080SSEM2</b>	<b>AKCU 1</b>	<b>11477</b>	<b>ECU V3 0</b>
<b>HF6850H9EM21</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6112E9EM21</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6652GEM21</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6100E9FCEM2</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6829A6EM1</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6851E9EM1</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>
<b>HF6100E9EM21</b>	<b>AKCU 1</b>	<b>11390</b>	<b>ECU V2 0</b>

